



REVISIONS			
REV	DESCRIPTION	DATE	APPROVED

**STEP 1**




CLEAN MATING SURFACES FREE OF GREASE

**STEP 2**




LINE UP THE TWO SCREWS ON GEARBOX COUPLER WITH HOLES

**STEP 3**




IF THE MOTOR HAS A KEYWAY, REMOVE IT

**STEP 4**




FIT THE MOTOR IN THE GEARBOX

**STEP 5**





MOUNT MOTOR TO GEARBOX WITH SCREWS AND LOCK WASHERS PROVIDED

**STEP 6**



TIGHTEN COUPLER SCREWS AND PLACE PROVIDED CAPS OVER HOLES

 <b>ANAHEIM AUTOMATION</b> 4985 E LONDON DRIVE ANAHEIM, CA. 92807		TITLE <b>GBPH GEARBOX TO MOTOR MOUNTING INSTRUCTIONS</b>	
THIS DRAWING OR DOCUMENT AND THE INFORMATION SET FORTH HEREIN ARE THE PROPERTY OF ANAHEIM AUTOMATION AND SHALL NOT BE USED OR DISCLOSED EXCEPT IN ACCORDANCE WITH ITS WRITTEN PERMISSION.		SIZE <b>C</b>	DATE <b>6-16-08</b>
REFERENCE DRAWINGS TOLERANCES UNLESS OTHERWISE SPECIFIED ALL DIM. IN INCHES UNLESS OTHERWISE SPECIFIED ANGLES $\pm$ .5 DEGREE		DRAWN <b>T. RAINES</b>	APPROVED 
MATERIAL FINISH		DRAWING NO. <b>AA5203</b>	REV. 1 OF 1
SCALE <b>1/1</b>		MODEL SHEET 1 OF 1	